KRAFTWERK
quality tools

Using-Instructions

EN

Electronic pocket digital level with 2 vials

0-90° / 0.1°



Art.2939

CE FC RoHS



® Registered Design

Applications



WARRANTY
We do not take responsibility for any damage caused by misuse.

CUSTOMER SERVICES
Contact your local importer of your specialized dealer to obtain address of our service department. You find our partners under
www.KRAFTWERKtools.com

From date of purchase receipt
2 YEARS GUARANTEE
on material- or production-defects

Please read these instructions carefully to ensure the safe and effective use of this tool.

Download Bedienungsanleitung / Téléchargement du mode d'emploi / Instructions download
Descarga de la instrucción de uso / Download de instruções de operação / Download del manuale

www.KRAFTWERKtools.com

Distribution:

User Instruction

On/Off : Turn on/off

Alt.Zero : Set any angle to 0° as reference

CAL : Refer Calibration instruction

MODE :
- Press to change display unit: ° (degree) / % (slope)
- Press & hold to freeze display value

⚠ CAUTION

2939 is calibrated in the factory for maximum accuracy (User can re-calibrate when necessary)

For first time use, remove the plastic strip to connect the battery

Calibration Instructions

1.a. Push ONCE on the CAL button then release, CAL1 (Display and Blink)

b. Place 2939 on a flat surface (e.g. Table)

2.a. Press MODE and release LCD display show count down (10,9,8…1), CAL 2 (Display and Blink)

b. Place 2939 reverse horizontal (180°). Press MODE & release, LCD display show count down, CAL 3 (Display and Blink)

c. Place 2939 vertically (-90°). Press MODE button and release LCD display show count down, CAL 4 (Display and Blink)

d. Place 2939 reverse vertically (+90°). Press MODE button and release LCD display show count down. **CALIBRATION DONE.**

NOTE : Ensure 2939 is kept still during Calibration

Calibration Picture



Glue